CARR - 731

1443 OLD MANCHESTER ROAD

mid-19th century

Westminster vicinity

private

1443 Old Manchester Road is an unusual farmhouse and highly interesting structure. It has not been remodeled and many of its early characteristics can still be seen. The general shape of the structure is unusual for this region through its rear addition covered by a catslide roof similar to building styles found in New England. The main facade is four bay wide with two entrances on the first story and six-over-six windows in the other bays. The exterior is covered in German siding and the siding below the full-length, one-story front porch is painted white--a characteristic traditionally found in German settled areas of Maryland and Pennsylvania.

UTM REFERENCES:

NEGATIVE FILE NUMBER:

(ARR-731

SUFVEY NUMBER:




DEPARTMENT OF PLANNING AND DEVELOPMENT

225. N. Center Street Westminster, Maryland 21157

WESTMINSTER PLANNING DISTRICT	Zone/Easting/Northing
FIELD SHEETHISTORIC RESOURCES SURVEY	U.S.G.S. QUAD. MAP: Westimm, ter
	PRESENT FORMAL NAME:
COUNTY: CARROLL FOWN: Westernster vicinity	ORIGINAL FORMAL NAME:
LOCATION: 1443 Old Manchester Road (MD 852)	PRESENT USE: Holding
TAX MAP 39 Block 12 P-19	ARCHITECT/ENGINEER:
COMMON NAME:	BUILDER/CONTRACTOR:
DUNCTIONAL TYPE: residure WNER: ROY C LEISTER DDRESS: 1423 OID MANCHESTER RD WESTMINSTER 21157	PHYSICAL CONDITION OF STRUCTURE: Excellent () Good () Fair () Poor (×)
CCESSIBILITY TO PUBLIC:	THEME:
es () No (×) Restricted () EVEL OF SIGNIFICANCE:	STYLE:
ocal () State () National () ENERAL DESCRIPTION:	DATE BUILT: early - to- mid 19th century
2. Wall Structure A. Wood: Log () Post and Beam (X) Balloo B. Wood Bearing Masonry: Brick () Stone (C. Iron () D. Steel () E. Other 3. Wall Covering: Weatherboard () German Sidi Wood Shingle () Shiplap () Aluminum () Asphalt Shingle Bonding Pattern: 4. Roof Structure) Concrete () Concrete Block ()
A. Truss: Wood (X) Iron () Steel () Comb. B. Other: 5. Roof Covering: Slate () Wood Shingle () Built Up () Rolled () Tile 6. Engineering Structure: 7. Other: Appendages: Porches (X) Towers () Cupolas () In Ells () Wings () Other: Roof Style: Gable (X) Hip () Shed () Flat () Saw Tooth () With Monitor () With In With False Front () Other: Sumber of Stories: Sumber of Bays: Handle (X) Iron () Steel () Comb. Built Up () Rolled () Tile Outpolas () In the Comb. Built Up () Rolled () In	Asphalt Shingle () Sheet Metal (x) e () Other: Dormers () Chimneys () Sheds ()
-pproximate bimensions:	
THREAT TO STRUCTURE: To Threat () Zoning () Roads () Development () Deterioration () Literation () Other:	LOCAL ATTITUDES: Positive () Negative () Mixed () Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPT	rion:
catalide roof nakes structure musual for this	Mer THE
bunan -siling arterior - painted white belo	w 1 st. full-length First souch
TO AMERICAN MADE IN THE TOTAL	
PERSON (ORNA SORE)	
PRINCIPAL ROBBAL MARK	
The Lagrange Section	The same of the sa
RELATED STRUCTURES: (Describe)	TO THE REAL PROPERTY.
AND THE PRINCE CONTRACTORS	
There is a second to the second of the secon	
STATEMENT OF SIGNIFICANCE:	
unusual early-tr-mid 19th century house	e - deserves further research to determore
its date of constancting original	Same of the control o
REFERENCES: 1862 Martenet's Map: 7	CA Daniel I I mod tel bace Leene
1877 LG & S Atlas: E. Brumnel Store?	
Character many of a second-one are	
CHDDOHNDING ENUIDONMENT.	
SURROUNDING ENVIRONMENT: Open Lane ()Woodland ()Scattered Buildings() Moderately Built Up ()Densely-Built Up () Residential () Commercial () Agricultural () Industrial () Roadside Strip Development () Other:	ORGANIZATION: DATE RECORDED:
	8 83





- 1. CARR-731 1443 OLD MANCHESTER ROAD
- 2. Carroll County, Maryland
- 3. Joe Getty
- 4. August 1983
- 5. Md. Historical Trust, Annapolis, Md.
- 6. North and west elevations (camera facing southeast)
- 7. 1/1